

ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Robert Cole	2. Log Date: 03/10/03	3. CCR #: 03-0164	4. Rev:	5. Tel: 301.925.0799	6. Rm #: 2110C	7. Dept. SE/HW
8. CCR Title: Upgrade Brocade Firmware at EDC						
9. Originator Signature/Date Robert Cole /s/ 03/10/03			10. Class II	11. Type: CCR	12. Need Date: 3/13/03	
13. Office Manager Signature/Date Randy Haynes /s/ 03/10/03			14. Category of Change: Update ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): N/A			17. Schedule Impact:		18. CI(s) Affected: SAN	
19. Release Affected by this Change: N/A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input checked="" type="checkbox"/> Other: NCR ECSed 35950						
23. Problem: (use additional Sheets if necessary) Fibre channel switch firmware may be responsible for data corruption documented in NCR ECSed35950.						
24. Proposed Solution: (use additional sheets if necessary) Update the firmware levels of the Brocade SAN switches to 2.6.0e, the latest STK certified version. See next sheet for installation instructions. File checksum: 483860272 3638660 brocade_firmware_v2.6.0e						
25. Alternate Solution: (use additional sheets if necessary)						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Data corruption will continue.						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:				30. Work Assigned To:	31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date):		Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
33. M&O CCB Chair (Sign/Date): Gary Gavigan /s/ 3/11/03		Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
34. ECS CCB Chair (Sign/Date):		Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS				

ADDITIONAL SHEET

CCR #: **Rev:** **Originator:**

Telephone: **Office:**

Title of Change:

Firmware upgrade instructions

Perform the following steps for each switch.1. Copy the firmware file to a location vaccessible from e0sas01

2. Execute the switchDisable command on the fibre channel switch

3. Execute the firmwareDownload command and respond to the prompts using the path to the firmware file, the FTP protocol, and the private IP address of p0sas01.

4. When the firmware download is complete, execute the command fastBoot to reboot the switch.

5. After the switch boots, execute the command switchEnable to re-enable the switch.